

How to Install NoTouch OS on LG Thin Clients

Using a **USB** pen drive or **PXE/Network** boot. Alternatively you can run NoTouch OS on the "Live" mode.



1. Preparation Set up your boot medium

USB Drive

To create a bootable USB drive you'll need the following:

- a. USB flash drive, at least 2GB in FAT/FAT32 format
- b. The Stratodesk NoTouch OS All-In-One package (ZIP file). Download it from the Stratodesk web site.

PXE Network


To do a PXE/Network installation you'll need the following:

- a. The Stratodesk NoTouch OS All-In-One package (ZIP file). Download it from the Stratodesk web site.
- b. Stratodesk Virtual Appliance installed and configured

2. Installation

a. Let the target machine boot from your boot medium

b. Immediately after boot, at the boot menu, type in "install"



```
ISOLINUX 6.03 ETCD Copyright (C) 1994-2014
Stratodesk
*****
**** NoTouch OS Live Boot / Installation ****
*****

live          ... Live Boot (Default)
install       ... Install to system disk

Diagnostic options:
live-verbose  ... Live Boot (Verbose boot)
install-verbose ... Install to system disk

https://www.stratodesk.com
US: Stratodesk Corp, San Francisco, California
EU: Stratodesk GmbH, Klagenfurt, Austria

For technical support please write to support
boot: install
```

c. Stratodesk GENESIS Main Menu will open. Select Install NoTouchOS option and hit ENTER



d. Next enter the serial number. For test purposes you can also enter a dummy S/N.

e. Then you will be asked if you are sure to install NoTouch on your Drive. Select "OK" and hit "Enter"

f. If everything goes well you will see a "Successful Installation!" message, and be asked to press "Enter" to continue

Reboot and Enjoy!